



NON-CONFORMITY REPORT (NCR)

PNG Offshore Vehicle Inspection and Verification



The below vehicle has been rejected from the PNG RTA Pre-Export Vehicle Appraisal for the noted non-conformities and is ineligible for registration in Papua New Guinea.

Please contact the Road Traffic Authority, www.rta.gov.pg

Details:

Client Details: Niugini Pacific International LTD T/AS Port
Moresby Motors
Chassis/VIN No.: WH35D-300189
Make: MAZDA
Model: TITAN

NCR No.: 20211129-781960

Date of Issue: 29/11/2021

Authorization: *Tatsuki Takasaki*

Inspection:

Date & Time: 25/11/2021 01:39 PM
Inspector: Kunihiro Oba
Year of Manufacture: 2002
Year of Registration: 200212
Body Type: DUMP TRUCK
Vehicle Type: Cargo, Goods Vehicle
Colour: BLUE
Passenger Capacity: 3
Fuel Type: Diesel
Auction Report: No
Maintenance Record: No

Location: YOKOHAMA, KANAGAWA
Weather: SUNNY
Engine Capacity: 4,330 cc/kw
Odometer: 165,278 km
Engine Number: JEVIC820564
RHD/LHD vehicle: RHD
Transmission: M/T
Drive: 2WD FR
Number of Doors: 2
Model Code: KK-WH35D
Euro 4 Compliant: No
(Japan 05) KK

NON-CONFORMITY DETAILS:

-	FLOOD DAMAGE
-	FIRE DAMAGE
-	STOLEN VEHICLE
X	EXCEEDING THE AGE LIMIT (Vehicles with a GVW not exceeding 3,500 kg: > 5 years / Other vehicles: > 15 years)
X	EMISSION STANDARD EURO 4 / JAPAN 05 NON-COMPLIANCE
-	ODOMETER FRAUD
-	CFC

COMMENT:



For Terms & Conditions please see www.JEVIC.com



NON-CONFORMITY REPORT (NCR)

PNG Offshore Vehicle Inspection and Verification



Chassis/VIN No.: WH35D-300189
Make: MAZDA
Model: TITAN

NCR No.: 20211129-781960
Date of Issue: 29/11/2021

Photographs:



Front Left



Front Right




Audio Dashboard



Rear Left



Rear Right



Seats Front




Engine Bay



Underneath Front



Seats Rear



Boot



Underneath Rear



Additional



PNG Offshore Vehicle Inspection and Verification

Certificate No. : 20211129-781960

Vehicle Make : MAZDA

Vehicle Model : TITAN

Date of Issue : 29/11/2021

Chassis No. : WH35D-300189

Window Sticker : N/A



5. Detailed description

Interior Equipment

Sunroof	No
Spare Key	No
Remote Key Lock	No
Power Steering	Yes
Tilt Steering	Yes
Cruise Control	No
Power Windows(s)	Working
Central Locking	Working
Leather Seats	No
Power Seats	No
Heated Seats	No
Clearance Sonar	No
Air Conditioning	Yes
Audio Visual	Exist
Navigation	No
Radio	Yes
CD	No
DVD	No
Cassette	No
iPod Link	No
SD Card	No
USB	No
HDMI	No
HIC	No
Other	
N/A	

Interior Condition

Interior Odour	None
Steering Wheel	Normal
Aftermarket	No
Gear Knob	Present
Aftermarket	No
Seat Driver	Normal
Aftermarket	No
Seat Passenger	Normal
Aftermarket	No
Seat Rear	Normal
Seat 3rd Row	N/A
Seat-Headrests	All Present
Floor Mats	2
Carpets	Yes
Pedals	Normal
Condition	
Roof Lining	Stain/Burn
Dashboard	No Damage
Instrument Panel	No Damage
Door Lining	
Driver	OK
Passenger	OK
Rear Right	N/A
Rear Left	N/A
Hatch	N/A

Mechanical

Gauge - Odometer	Working
Gauge - Fuel	Working
Gauge - Temp	Working
Gauge - Tach	Working
Warning Light(s)	OK
Warning Lights on	-
Horn	Working
Engine - Start	Yes
Engine - Idle	Smooth
Belt Noise	Not Present
Wipers(s) Front	Working
Wipers(s) Rear	N/A
Washers(s) Front	Working
Washers(s) Rear	N/A
Muffler Noise	Normal
Emission Test	Pass
Engine Oil	Normal
Condition	Normal
Brake Fluid	Normal
Condition	Normal
Oil Leak (Serious)	No
Open/Closing OK	
Drivers Door	OK
Passengers Door	OK
Rear Right Door	N/A
Rear Left Door	N/A
Boot/Hatch	N/A
Bonnet	OK
Fuel Flap	N/A
Glove Box	Yes

Side Mirrors	
Automatic	
Left Side	OK
Right Side	OK
Rear View Mirror	Normal
Lever - Wiper	Normal
Lever - Indicators	Normal
Lever - Lights	Normal
Switches - Lights	Normal
Switches - Audio	Normal
Switches - Aircon	Normal

Seat Belts	
Driver	OK
Passenger	OK
Rear Right	N/A
Rear Left	N/A
Rear Center	N/A
3rd Seats	-

Lights OK	
Headlights	OK
Tail	OK
Side	OK
Indicators	OK
Brake	OK
Reverse	OK
Fog	OK
Licence Plate	OK
Interior	OK
Other Lights Not Working	
N/A	
Window Condition	OK

Safety Equipment

Drivers Airbag	Yes
Passenger Airbag	No
Curtain Airbag	No
Knee Airbag	No
ABS System	No
Handicap Options	No
Spare Tyre	Yes
Tool Kit	Yes
Jack	Yes
Safety Triangle	No

Tyre(s)

Front Right Tread	7 mm
Front Right Type	A
Front Left Tread	7 mm
Front Left Type	A
Rear Right Tread	4 mm
Rear Right Type	A
Rear Left Tread	4 mm
Rear Left Type	A
Spare Tread	3 mm
Spare Type	B

Exterior Equipment

Tinted Windows	No
Body Kit	No
Alloy Wheels	No



Biosecurity

Exterior/Interior	OK
-------------------	----

Air Conditioner Gas

CFC	N/A
-----	-----

Vehicle Damage / Underside Inspection



A = Scratch
B = Bent
H = Hole

P = Painted
R = Rust
T = Tear

U = Dent
W = Wave
X = Damage
V01012020_PG_PSI_NCR